Psychrometers and Hygrometers

Psychrometers



1328 Sling Psychrometer

- •20° to 120°F in 1° Divisions
- •Accuracy: ±1°F
- •9" Tubes
- •Folding Swivel Handle
- Mercury Filled
- ·Special Molded Case
- •Stainless Steel Back
- •°C (1328C) and Permacolor™ (1328P) Versions Available

1328A Spare Tubes for 1328 **1328CA** Spare Tubes for 1328C **1328PA** Spare Tubes for 1328P



1330 Pocket Sling Psychrometer

- •20° to 120°F
- Accuracy: ±1°F
- •Mercury Filled
- •High Impact Plastic
- •White on Black Scale Markings
- •°C (1330C) and Permacolor™ (1330P) Versions Available

1330NA Spare Tubes for 1330 **1330NCA** Spare Tubes for 1330C **1330NPA** Spare Tubes for 1330P, Button Top

Hygrometers



5522 Mason's Hygrometer

•30° to 120°F

- •Accuracy: ±1.5°F
- Mercury Filled
- •Wet Bulb Dry Bulb
- •Boxed With Wicks and Humidity Tables

5522A Replacement Tube and Scale for 5522 **5522N** Replacement Cistern for 5522



5525 Mason's Hygrometer

- •0° to 130°F
- •Accuracy: ±2°F
- •Permacolor™ Filled
- •Wet Bulb Dry Bulb

5525N Water Cistern for 5525



5565 Dial Hygrometer and Thermometer

- •10° to 130°F
- •5% to 90% RH
- •Temperature Accuracy: ±1.8°F
- •Humidity Accuracy: ±5% between 25%-90% RH
- •Large 5["] Dial
- •Synthetic Hair RH Sensor

Pressure Calibrators

Flow Transmitters, Pneumatic Controllers, Low Pressure Gauges, Pneumatic Transmitters

The calibrator consists of sphygmomanometer type (blood pressure) precision gauge accurate to ±1% with a squeeze bulb for applying pressure manually and a precision-machined hand-adjusted valve to hold and relieve the calibrating pressure. A flexible hose and a 3/16" tube - ¼" NPT compression fitting is supplied for quick and easy connection to unit being tested.



44S 369 Pressure Calibrator

44S 390 Pressure Calibrator

- •0-160" Water Indicating Gauge
 •Includes Carrying Case
- -
- •0-18 SIG Indicating Gauge
- •Includes Carrying Case